

To: Rodriguez, Dante[Rodriguez.Dante@epa.gov]; Dave Davis[drdavis@blm.gov]
From: Jeryl Gardner
Sent: Wed 3/22/2017 8:08:40 PM
Subject: FW: Photolog of Yerington FMS
[Pond Photolog 021517.pdf](#)
[Pond Photolog 022117.pdf](#)

....
>>>>

FYI: Before and after rain photos from February.

I have no questions after reviewing and comparing the photos.

Jeryl R. Gardner, P.E., C.E.M.

Abandoned Mine Lands Program Manager

Bureau of Corrective Actions, NDEP
901 S. Stewart St., Ste 4001
Carson City, NV 89701
775-687-9484
jgardner@ndep.nv.gov



From: Oman, Jack [mailto:Jack.Oman@bp.com]
Sent: Wednesday, March 22, 2017 12:40 PM
To: Jeryl Gardner
Cc: John Batchelder ; Phelps, Travis (Travis.Phelps@arcadis.com)
Subject: Photolog of Yerington FMS

Jeryl,

As we discussed, attached are photos documenting site conditions pre- and post-rain event from February. Photos were taken Feb 15, and Feb 21 respectively. During this time the site received approximately 0.2 to 0.3 inches of rain.

Let us know if you have any questions or would like to discuss further.

Thanks,

-jack